


EAN: 4015474172913
static.hansa.com/51092173

Pièces de rechange



SP51092173

	Nom	Code
1	Levier, L=50, M5 IG	59913335
1.1	Vis, M5x35	59913299
1.4	Joint, d 3x1.5	59913100
1.5	Capuchon Chrome	59913332
1.5	Capuchon Blanc Arrêté	59913334
1.5	Capuchon Noir Arrêté	59913333
2	Chape Chrome	59913364
2.1	Bague glissante	59913363
2.2	Joint, d 38x2	59913212
2.3	Rosace Chrome	59913375
7	Rosaces Chrome	59913444
8	Bec, L=200 Chrome	59913441
8.2	Mamelon de raccordement, M15x1,5xG1/2, SW 8	59913241
8.3	Aérateur, M18.5x1, TJ	59913366
8.4	Clé pour aérateur, M18.5	59913367