


EAN: 4057304020421
static.hansa.com/5437220780

Ersatzteile

SP54372207CLR



	Name	Art.-Nr.
01	Spann-Mutter, M34x1.5	1012133V
02	Kartusche, 3.0	1014428V
03	Befestigungssatz	59913479