


EAN: 4015474078727
static.hansa.com/01949273

Pièces de rechange

SP01692173



| | Nom | Code |
|------|--|----------|
| 1 | Levier long, L=138 Chrome | 01880076 |
| 1 | Levier, L=87 mm | 59914195 |
| 1.1 | Vis, M5x8, SW2.5 | 59904755 |
| 1.2 | Kit de joints pour bec | 59904778 |
| 1.3 | Capuchon Gris | 59912112 |
| 2 | Chape Chrome | 59912638 |
| 3 | Vis Loop, M50x1, SW45 | 59904775 |
| 3.1 | Joint, d 43x2.5 | 59911166 |
| 4 | Cartouche, 4.8 eco | 59904601 |
| 4.1 | Hot water limiter | 59904759 |
| 5.1 | Vis, M6x12, AF2.5 | 59904804 |
| 8.1 | Joint, d 15x2.5 | 59910423 |
| 8.2 | Limiteur | 59910421 |
| 8.2 | Vis, M6x10, 2,5 | 59911435 |
| 8.3 | Limiteur | 59910422 |
| 8.4 | Ensemble d'entretien | 59912230 |
| 8.5 | Emptying valve | 59912483 |
| 10 | Bec, L=235 Chrome | 59910417 |
| 10 | Bec, L=96 Chrome | 59910419 |
| 10 | Bec, L=170 Chrome | 59911183 |
| 10 | Bec, L=145 Chrome | 59911380 |
| 10 | Bec, L=96 (2019-) Chrome | 59914765 |
| 10 | Bec, L=170 (2019-) Chrome | 59914766 |
| 10 | Bec, L=235 (2019-) Chrome | 59914767 |
| 11 | Aérateur, M24x1 Z Chrome | 59906826 |
| 11 | Aérateur, M24x1 STD PL HC A Laminar (2013-) Chrome | 59914054 |
| 12 | Écrou de connexion, G3/4, AF30 | 59902230 |
| 12.1 | Siège, G1/2, L, WAF10 | 59904618 |
| 12.2 | Joint, 23.9x15.2x2 | 59902689 |
| 13 | Excentrique, G3/4xG1/2 Chrome | 59904793 |
| 13.1 | Rosaces Chrome | 59904796 |
| 13.3 | Connecteur excentrique, G3/4xG1/2, DN15 | 59910254 |
| 14 | Racc excentrique, vis pointeau et rosace, G1/2xG3/4 Chrome | 59902034 |