


EAN: 4015474259355
static.hansa.com/48102131

Pièces de rechange

SP58102101



	Nom	Code
1.1	Écrou de connexion, G3/4, AF30	59902230
1.2	Nipple	59911075
1.3	Joint, 23.9x15.2x2	59902689
1.4	Joint filtre, G3/4	59911076
2	Connecteur excentrique, G3/4xG1/2, DN15	59910254
2.2	Silencieux	59904792
2.4	Rosaces Chrome	59913432
2.5	Rosace Chrome	59912651
3	Croisillon d'ouverture Chrome	59913939
3.1	Cache	59913850
3.2	Vis, M4x8	59913851
3.3	Bague de réglage	59913940
4	Tête	59913936
4.1	Vis, SW30	59913941
4.2	Broche Chrome	59913689
4.4	Joint, d 32x2	59912803
4.5	La partie intérieure	59913942
5	Croisillon réglage de température Chrome	59913938
5.1	Temperature adjustment limiter	59913937
5.2	Locking screw, 38°	59913919
6	Cartouche thermostatique, 3.3	59913871
6.1	Vis, M6x9.5	59901609
7	Clapet anti-retour, DN10 (2016-)	59914425
9	Aérateur, M24x1 D Chrome	59911829