


EAN: 4015474254572  
[static.hansa.com/52433273](http://static.hansa.com/52433273)

## Pièces de rechange

### SP52433273



|      | Nom   | Code     |
|------|---|----------|
| 1    | Levier Chrome   | 59913840 |
| 1    | Levier Chrome   | 59914629 |
| 1.1  | Vis, M5x8, SW2.5  | 59904755 |
| 1.3  | Capuchon Gris   | 59912112 |
| 2    | Chape, 33x3 mm Chrome                                       | 59912504 |
| 3    | Écrou de maintien, M40x1                                    | 1003409V |
| 4    | Cartouche, 3.5 Eco  | 59912324 |
| 4    | Cartouche, 3.5 Classic                                      | 59913075 |
| 4.1  | Temperature adjustment limiter                              | 59912325 |
| 4.3  | Joint, d 28.24x2.62 <b>Arrêté</b>                           | 59912590 |
| 4.4  | Joint, d 10.10x1.60 <b>Arrêté</b>                           | 59905072 |
| 5.1  | Tirette de vidage   | 59913587 |
| 5.2  | Joint   | 59904624 |
| 5.3  | Bague   | 59914591 |
| 5.5  | Fixing plate  | 59904765 |
| 5.6  | Vis, M8x1, SW13   | 59904766 |
| 5.7  | Ensemble de fixation  | 59912113 |
| 5.8  | Flexible d'alimentation, L=430, G3/8-M10x1 RH <b>Arrêté</b> | 59913213 |
| 5.9  | Flexible d'alimentation, L=430, G3/8-M10x1                  | 59912515 |
| 5.10 | Joint, d 7.65x1.78  | 59902337 |
| 5.11 | Joint, 9.5x14.4x2   | 59912551 |
| 5.12 | Vis, M8x1, L=140  | 59912474 |
| 6    | Aérateur, M24x1, 6 l/min Chrome                             | 59913727 |
| 6.2  | Joint boule pour mitigeur bidet                             | 59910952 |
| 7    | Vidage Chrome   | 59904620 |
| 7    | Vidage, (2019-) Chrome                                      | 59914764 |
| N.I. | Clef, SW30/34   | 59912108 |