


EAN: 4015474269071
static.hansa.com/52682203

Pièces de rechange

SP52682203



| | Nom | Code |
|-----|---|-----------------|
| 1 | Levier Chrome | 59913840 |
| 1 | Levier Chrome | 59914629 |
| 1.1 | Vis, M5x8, SW2.5 | 59904755 |
| 1.3 | Capuchon Gris | 59912112 |
| 2 | Chape, 33x3 mm Chrome | 59912504 |
| 2.1 | Joint, 45x35.5x5.4 | 59913651 |
| 3 | Écrou de maintien, M40x1 | 1003409V |
| 4 | Cartouche, 3.5 Classic | 59913075 |
| 5.1 | Bague | 59914591 |
| 5.2 | Ensemble de fixation | 59912113 |
| 5.3 | Flexible d'alimentation, L=430, G3/8-M8x1 | 59913964 |
| 5.4 | Joint, 6x1.4 | 59913266 |
| 5.5 | Joint, 9.5x14.4x2 | 59912551 |
| 5.6 | Vis, M8x1, L=140 | 59912474 |
| 5.7 | Tuyau de raccordement, M8x1-M14x1, L=214 | Arrêté 59914035 |
| 5.8 | Connecteur, G1/2xM14x1 | Arrêté 59914180 |
| 6 | Aérateur, M24x1, 6 l/min Chrome | 59913727 |