


EAN: 4015474076761  
[static.hansa.com/54063205](https://static.hansa.com/54063205)

## Pièces de rechange

### SP54063205



	Nom	Code
1	Levier <b>Arrêté</b>	5990548875
1.1	Vis, M5x8, SW2.5	59904755
1.2	Kit de joints pour bec	59904778
1.3	Capuchon Gris	59912112
2	Chape Chrome	59912638
3	Vis Loop, M50x1, SW45	59904775
3.1	Joint, d 43x2.5	59911166
4	Cartouche, 4.8 eco	59904601
4.1	Hot water limiter	59904759
5.2	Joint	59904624
5.3	Joint, 37x48x3.5	59911422
5.5	Fixing plate	59904765
5.6	Vis, M8x1, SW13	59904766
5.7	Ensemble de fixation	59910749
5.8	Tuyau	59912709
5.9	Flexible d'alimentation, L=430, G3/8-M10x1	59912515
5.10	Joint, 9.5x14.4x2	59912551
5.11	Joint, d 7.65x1.78	59902337
5.12	Vis, M8x1, L=140	59912474
6	Aérateur, M24x1 STD HC A Chrome	59902366
6.1	Aérateur, M22/24 A	59902081
6.2	Joint boule pour mitigeur bidet	59910952
7	Vidage Chrome	59904620
N.I.	Tuyau de raccordement, 10xG3/8 Chrome <b>Arrêté</b>	59912332
N.I.	Tuyau de raccordement, L=430, M10x1	59912550