


EAN: 4057304020421  
[static.hansa.com/5437220780](https://static.hansa.com/5437220780)

## Pièces de rechange

### SP54372207CLR



|    | Nom                        | Code     |
|----|----------------------------|----------|
| 01 | Écrou de maintien, M34x1.5 | 1012133V |
| 02 | Cartouche, 3.0             | 1014428V |
| 03 | Ensemble de fixation       | 59913479 |