


EAN: 6414150103650  
[static.hansa.com/5447220780](https://static.hansa.com/5447220780)

## Ersatzteile

### SP54372207CLR



	Name	Art.-Nr.
01	Spann-Mutter, M34x1.5	1012133V
02	Kartusche, 3.0	1014428V
03	Befestigungssatz	59913479