


EAN: 4015474078406
static.hansa.com/54859103

Pièces de rechange



SP54859105

	Nom	Code
1	Levier Arrête	5990548875
1.1	Vis, M5x8, SW2,5	59904755
1.2	Kit de joints pour bec	59904778
1.3	Capuchon Gris	59912112
2	Rosaces, d 205 mm Chrome	59911969
2.1	Chape Chrome	59904820
2.3	Vis, M5x65 Chrome	59904847
2.5	Joint en caoutchouc	59912232
2.6	Joint, 55x2	59912543
N.I.	Rallonge pour mitigeur encastrés, 20 mm	59904983