


EAN: 4015474263086  
[static.hansa.com/54912273](http://static.hansa.com/54912273)

## Pièces de rechange

### SP54912273



	Nom	Code
1	Levier, 2.5 Chrome	59913985
1.1	Vis, M5x8, SW2.5	59904755
1.3	Butée de réglage Chrome	59913762
2	Chape Chrome	59913957
3	Écrou de maintien, M32x1, SW24	59913958
4	Cartouche, 2.5	59913914
5.1	Set de fixation pour bec	59914027
5.2	Joint, 35x2.5	59905020
5.3	Joint, 48x33.5x2	59902283
5.4	Plaque de fixation	59910008
5.8	Ensemble de fixation	59913479
5.9	Flexible d'alimentation, M18x1,G3/8, L=650	59914036
5.10	Tuyau de raccordement, M8x1-M14x1, L=214	Arrêté 59914035
5.11	Joint, 6x1.4	59913266
5.12	Joint, 9.5x14.4x2	59912551
6	Bec Chrome	Arrêté 59914026
6.1	Vis, M4x8	59913989
6.2	Mamelon de raccordement	59914029
7.1	Bec extractible Chrome	59914033
7.2	Clapet anti-retour, DN8	59914030
7.4	Fitting ring for aerator Chrome	59913654
7.5	Aérateur, M18.5x1 HC TJ B, (2018-)	59914031
8	Rosaces, d 55 mm Chrome	59913963
9	Tuyau, L=1400	59914032
9.1	Adaptateur	59914028
9.2	Counterbalance	59914039