


EAN: 4015474261433  
[static.hansa.com/57152201](http://static.hansa.com/57152201)

## Pièces de rechange

### SP57152201



	Nom	Code
1	Levier, 50 mm, d 7 mm Chrome	59913097
1.1	Goupille, M5x23, SW2.5	59913955
1.4	Joint, d 3x1.5	59913100
1.5	Capuchon Chrome	59913956
2	Chape Chrome	59913957
3	Écrou de maintien, M32x1, SW24	59913958
4	Cartouche, 2.5	59913914
4.1	Vis, M4x4	59901027
5.1	Tirette de vidage Chrome	59913959
5.2	Joint	59904624
5.3	Joint, 35x2.5	59905020
5.7	Ensemble de fixation	59913371
5.8	Flexible d'alimentation, L=430, G3/8-M8x1	59913964
5.9	Joint, 6x1.4	59913266
5.10	Joint, 9.5x14.4x2	59912551
6	Bec Chrome	59913960
6.1	Aérateur, M24x1	59913132
6.1	Aérateur, M24x1 HC SSR-STD	59914015
6.2	Fitting ring for aerator	59914007
6.2	Fitting ring for aerator, M24x1, SW17, (2019-)	59914744
6.6	Vis, M4x7	59902075
6.7	Set de fixation pour bec	59911884
7	Vidage Chrome	59904620
8	Rosaces, d 55 mm Chrome	59913963
N.I.	Butée de réglage Chrome	59911840