


EAN: 4057304019340
static.hansa.com/92012219

Pièces de rechange

SP92012009



	Nom	Code
01	Aérateur, M24x1 HC PCA 7.0 l/min Chrome	1016723V
02	Valve magnétique	1008658V
03	Sensor, 3/9 V, Bluetooth	1012464V
04	Ensemble de fixation	59914475
N.L.	Piles, 1,5 V AA Lithium	59914136