


EAN: 4057304020414
static.hansa.com/5437220733006

Pièces de rechange



SP5437220733006

	Nom	Code
01	Levier Mat noir	1017996V-33
02	Écrou de maintien, M34x1.5	1012133V
03	Cartouche, 3.0 cold start	1014430V
04	Ensemble de fixation	59913479